

Inspection Photos
Location Name: Howard USX-A 9-13
Location ID: 306348



Photo 1: Wellhead



Photo 2: Tank Battery

Inspection Photos
Location Name: Howard USX-A 9-13
Location ID: 306348



Photo 3: Fence around separator in disrepair.



Photo 4: Unused equipment.