

Inspection Photos

Location Name: HESTER-67N66W /31SWNW

Location #: 306743



Photo #1

Hester 31-23 (05-123-25183) Wellsite

Plugged & Abandoned | PA

Casing NOT Cut & Capped | No temporary Safety Cap

