

Final Reclamation and Stormwater Inspection

February 1, 2019

Operator: RUTH* ULA PEARL - 90902

Location ID: 319655

Inspection Document #: 674902543

Weld County, CO

NENE Section 21 T3S R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RUTH* ULA PEARL /3S64W21
Location ID: 319655



Photo 1. Photo taken looking into the location, facing West. Photo depicts equipment left on location.



Photo 2. Photo taken looking into the location, facing West. Photo depicts equipment left on location.

Inspection Photos
Location Name: KERR MCGEE /1N65W16
Location ID: 317723



Photo 3. Photo taken from the location, facing North. See comments from Photo 1.



Photo 4. Photo taken from the location, facing East. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /1N65W16
Location ID: 317723



Photo 5. Photo taken from the location, facing South. See comments from Photo 1.



Photo 6. Photo taken from the location, facing East. See comments from Photo 1.