

Inspection Photos
Location Name: RH FARMS /II33-14D
Location #: 323323



Colorado Oil & Gas Conservation Commission
40.52566, -104.79149, 1486.0m, 296°
2019/02/07 10:56:19 AM

Photo #1

RH Farms II33-11D (05-123-34614) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.52398, -104.7912, 1468.0m, 351°
2019/02/07 11:29:39 AM

Photo #2

Battery

Guard #1

RH Farms II33-11D, II33-12D, II33-14D, II33-25D

Shut-down