

Inspection Photos
Location Name: RUSCO-67N66W /23NWSE
Location #: 306621



Photo #1
Rusco 33-23 (05-123-25026) Wellsite
Shut-In | SI



Photo #2
Rusco 33-23, 43-23 Battery
Shut-down