

Inspection Photos
Location Name: LOCKMAN-66N66W /4SENE
Location #: 306526



Photo #1

Lockman 4-14 (05-123-24844) Wellsite

Shut-In | SI

No Orange tag posted for SI/TA status



Photo #2

Lockman 4-14 Battery

Shut-Down