

**Inspection Photos**  
**Location Name: GILLAM TRIGOOD 14**  
**Location ID: 05-103-07182**  
**Inspection: 679702971**



**Photo 1. Location looking west.**



**Photo 2. Location looking east.**

## Inspection Photos

Location Name: GILLAM TRIGOOD 14

Location ID: 05-103-07182

Inspection: 679702971



**Photo 3. Venting.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources