

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/08/2019

Submitted Date:

02/11/2019

Document Number:

679702973

FIELD INSPECTION FORM

Loc ID 335952 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10447
Name of Operator: URSA OPERATING COMPANY LLC
Address: 1600 BROADWAY ST STE 2600
City: DENVER State: CO Zip: 80202

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|----------------------------|---------------------------------|
| Knudson, Dwayne | 970-456-3335 | dknudson@ursaresources.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------------|-------------|
| 297345 | WELL | XX | 09/07/2018 | LO | 103-11325 | Boies Ranch B-19N FED 42C-19-02-97 | ND |
| 297346 | WELL | XX | 09/07/2018 | LO | 103-11326 | Boies Ranch B-19N FED 22C-19-02-97 | ND |
| 297347 | WELL | XX | 09/07/2018 | LO | 103-11327 | Boies Ranch B-19N FED 22B-19-02-97 | ND |
| 300595 | WELL | XX | 09/07/2018 | LO | 103-11444 | Boies Ranch B-19N FED 42B-19-02-97 | ND |
| 300596 | WELL | XX | 09/07/2018 | LO | 103-11445 | Boies Ranch B-19N FED 42D-19-02-97 | ND |
| 300598 | WELL | XX | 09/07/2018 | LO | 103-11446 | Boies Ranch B-19N FED 22A-19-02-97 | ND |
| 300600 | WELL | XX | 09/07/2018 | LO | 103-11447 | Boies Ranch B-19N FED 21D-19-02-97 | ND |

General Comment:

[Routine well inspection.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--------------------|-------|--|
| | Type OTHER | | |
| | Comment: Well pad. | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 855-625-9922 | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 297345 Type: WELL API Number: 103-11325 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 297346 Type: WELL API Number: 103-11326 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 297347 Type: WELL API Number: 103-11327 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 300595 Type: WELL API Number: 103-11444 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 300596 Type: WELL API Number: 103-11445 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 300598 Type: WELL API Number: 103-11446 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: No visual evidence this well is drilled on the pad.

Corrective Action: _____ Date: _____

Facility ID: 300600 Type: WELL API Number: 103-11447 Status: XX Insp. Status: ND

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | | Compaction | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------|---|
| 679702974 | inspection photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4730398 |