

Inspection Photos

2/08/2019

Operator: NOBLE ENERGY INC - 100322

Location ID: 432936

Inspection Doc. Number: 682504506

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the west end of the location, facing north. Photos 1-4 provide an overview of the location from north, northeast, southeast to south.



Photo 2: See comments under photo 1.



Photo 3: See comments under photo 1.



Photo 4: See comments under photo 1.



Photo 5: Photo taken from the east end of the location, facing north. Photo shows vehicle tracks over the interim areas, leading from the east end of the pad to the north. This does not comply with 1002.e, surface disturbance minimization.



Photo 6: Photo taken from the east end of the location, facing west. Photo shows vehicle tracks over the interim areas, leading from the east end of the location to the southeast corner of the pad. This does not comply with 1002.e, surface disturbance minimization.



Photo 7: Photo taken from the southwest end of the location, facing southwest. Photo shows vehicle tracks over the interim areas from the pad. This does not comply with 1002.e, surface disturbance minimization.



Photo 8: Photo taken from the west end of the pad, facing west. Photo shows vehicle tracks over the interim areas from the pad. This does not comply with 1002.e, surface disturbance minimization.




Photo 9: 2013 (most current available) Google Earth aerial image. Inspector mapped a disturbance area of 1.13 acres via a Trimble GPS unit. This appears to exceed the approved Form 2A for the permitted disturbance area post interim reclamation (1 acre).