

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2019

Submitted Date:

02/11/2019

Document Number:

682504496**FIELD INSPECTION FORM**

Loc ID 421702 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421701	WELL	PR	02/23/2012	OW	123-33023	Rohn PC LD 16-96HN	RI

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective action\(s\) from previous inspections that have not been addressed are still applicable.](#)

Inspected Facilities									
Facility ID:	421701	Type:	WELL	API Number:	123-33023	Status:	PR	Insp. Status:	RI
Producing Well									
Comment:	PR Well, interim reclamation and stormwater inspection.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____ Pass _____

Comment [Fencing along perimeter of location.](#)

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____ Pass _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____ Pass _____

Comment [No waste or debris found on location or reclamation area.](#)

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____ Pass _____

Comment [No unused/unneeded equipment/materials found being stored on location or reclamation area.](#)

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ In _____	Production areas stabilized ? _____ Pass _____
1003c. Compacted areas have been cross ripped? _____	
1003d. Drilling pit closed? _____	Subsidence over on drill pit? _____
Cuttings management: _____	
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____ In _____	
Production areas have been stabilized? _____	Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____
Perennial forage re-established _____	
<u>Non-Cropland</u>	
Top soil replaced _____	Recontoured _____
80% Revegetation _____	
1003e. INTERIM VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	
1003 f. Weeds Noxious weeds? _____	
Comment	Current disturbance area of the pad is 1.77 acres (Mapped via GPS on 2/8/2019); this appears to be in compliance with the approved Form 2A for the permitted disturbance area post interim reclamation. Operator does not appear to have saved topsoil (stored topsoil on the location) for future reclamation efforts. COGCC Staff recommends leaving enough topsoil stockpiled for final reclamation. Interim reclamation appears to be in process, though areas of undesirable weedy plant species such as Russian thistle evident; Snow cover prevented an accurate assessment of reclamation and a follow-up inspection will need to be conducted in a future growing season to evaluate compliance with reclamation standards.
Corrective Action	<div style="border: 1px solid black; height: 20px;"></div>
Date	_____
Overall Interim Reclamation In Process	
<u>Final Reclamation/ Abandoned Location:</u>	
Date Final Reclamation Started: _____	Date Final Reclamation Completed: _____
Final Land Use: RANGELAND _____	
Reminder: _____	
Comment: <div style="border: 1px solid black; height: 20px;"></div>	
Well plugged _____	Pit mouse/rat holes, cellars backfilled _____
Debris removed _____	No disturbance /Location never built _____
Access Roads Regraded _____	Contoured _____
Gravel removed _____	Culverts removed _____
Location and associated production facilities reclaimed _____	
Locations, facilities, roads, recontoured _____	
Compaction alleviation _____	
Dust and erosion control _____	
Non cropland: Revegetated 80% _____	Cropland: perennial forage _____
Weeds present _____	Subsidence _____
1004.d. FINAL VEGETATION TRANSECT	
TRANSECT RESULTS OF DISTURBED AREA% _____	
TRANSECT RESULTS OF REFERENCE AREA% _____	
TOTAL % OF DESIRABLE VEGETATION COVER _____	
VEGETATIVE COVER _____	

Inspector Name: Trujillo, Aaron

Comment:			
Corrective Action:			Date
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>	Multi-Well Location <input type="checkbox"/>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682504497	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4731055