

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2019

Submitted Date:

02/11/2019

Document Number:

689702611**FIELD INSPECTION FORM**Loc ID 334409 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296856	WELL	PR	04/16/2008	GW	045-16176	WILLIAMS SG 12-35	PR
296857	WELL	PR	04/16/2008	GW	045-16177	WILLIAMS SG 412-35	PR
296858	WELL	PR	07/01/2008	GW	045-16178	WILLIAMS SG 512-35	PR
296859	WELL	PR	04/16/2008	GW	045-16179	WILLIAMS SG 312-35	PR
296860	WELL	PR	04/16/2008	GW	045-16180	WILLIAMS SG 22-35	PR
296861	WELL	PR	04/16/2008	GW	045-16181	WILLIAMS SG 322-35	PR
296862	WELL	PR	04/16/2008	GW	045-16182	WILLIAMS SG 422-35	PR
296863	WELL	PR	04/16/2009	GW	045-16183	WILLIAMS SG 522-35	PR

General Comment:

Routine FIU General Field Inspection

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>296856</u>	Type:	<u>WELL</u>	API Number:	<u>045-16176</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296857</u>	Type:	<u>WELL</u>	API Number:	<u>045-16177</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296858</u>	Type:	<u>WELL</u>	API Number:	<u>045-16178</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296859</u>	Type:	<u>WELL</u>	API Number:	<u>045-16179</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296860</u>	Type:	<u>WELL</u>	API Number:	<u>045-16180</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296861</u>	Type:	<u>WELL</u>	API Number:	<u>045-16181</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296862</u>	Type:	<u>WELL</u>	API Number:	<u>045-16182</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>296863</u>	Type:	<u>WELL</u>	API Number:	<u>045-16183</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>