

Inspection Photos
Location Name: LORECITO 5-6
API #: 05-071-07575
Insp. Doc. # 695100166



PHOTO 1: WELLHEAD



PHOTO 2: WELL SIGN/METER HOUSE

Inspection Photos
Location Name: LORECITO 5-6
API #: 05-071-07575
Insp. Doc. # 695100166



PHOTO 3: STAINED SOIL AROUND WELLHEAD



PHOTO 4: UNUSED EQUIPMENT STORED ON LOCATION