

Inspection Photos  
Location Name: LORECITO 3-6  
API #: 05-071-06974  
Insp. Doc. # 695100170



PHOTO 1: WELLHEAD

PHOTO 2: WELL SIGN/METER HOUSE

**Inspection Photos**  
**Location Name: LORECITO 3-6**  
**API #: 05-071-06974**  
**Insp. Doc. # 695100170**



**PHOTO 3: APPEARS SEPARATOR IS BEING DRAINED ON LOCATION.**

**PHOTO 4: GRASS OFF EDGE OF LOCATION APPEARS TO BE WASHED OVER BY FLUID DRAINED FROM SEPARATOR.**

**Inspection Photos**  
**Location Name: LORECITO 3-6**  
**API #: 05-071-06974**  
**Insp. Doc. # 695100170**



**PHOTO 5: RAINBOW SHEEN ON STANDING WATER NEAR GAS  
METER HOUSE**

