

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Photo 1: Wellhead



Photo 2: Tank Battery

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Colorado Oil & Gas Conservation Commission
40°22'50", -104°45'34", 1437.1m, 87°
02/11/2019 02:25:28 PM

Photo 3: Fluid leaking inside west gas meter house.



Colorado Oil & Gas Conservation Commission
40°22'50", -104°45'34", 1432.4m, 327°
02/11/2019 02:26:57 PM

Photo 4: Inadequate berm

Inspection Photos
Location Name: Strong 2-8
Location ID: 332565



Colorado Oil & Gas Conservation Commission
40°22'51", -104°45'33", 1436.7m, 252°
02/11/2019 02:43:46 PM



Colorado Oil & Gas Conservation Commission
40°22'50", -104°45'34", 1436.5m, 135°
02/11/2019 03:12:02 PM

Photo 5: Labeling of tank contents and capacity not visible to road.

Photo 6: Tank to far left not adequately labeled with contents/capacity.