

Inspection Photos
Location Name: ROWE-66N66W /13SWSW
Location #: 319557



Colorado Oil & Gas Conservation Commission
40.48321, -104.73173, 1443.0m, 4°
2019/02/11 03:43:40 PM

Photo #1
Rowe 13-1 (05-123-11471) Wellsite
Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.48272, -104.73166, 1430.0m, 343°
2019/02/11 04:04:56 PM

Photo #2
Rowe 13-1 Battery
Shut-down