

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001926



Photo of location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001926



Tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001926



Wellhead sign.

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001924



Unused Equipment stored on location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001926



Unused not tagged riser



Unused untagged riser out in location and could get run over

GORDON ENGINEERING INC

Api # 05-077-08508

Inspection # 675001926



Unmarked untagged riser on location where it could get hit by vehicle's



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources