

Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 327343

Inspection Document #: 674902549

Weld County, CO

NESW Section 22 T3N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /3N65W22
Location ID: 327343



Photo 1. Photo taken from the access road looking into the location, facing East. Appears Operator has not performed any final reclamation activities with equipment and gravel still on location.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos
Location Name: NOBLE ENERGY INC /3N65W22
Location ID: 327343



Photo 3. Photo taken from the location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the location, facing North. See comments from Photo 1.