

Inspection Photos
Location Name: FLATIRON-66N66W /36NWSE
Location #: 323190



Photo #1

Flatiron 10-36 (05-123-12686) Wellsite

Temporarily Abandoned | TA

No Orange tag posted for SI/TA status



Photo #2

Flatiron 10-36 Battery

Shut-down

