

Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 318026

Inspection Document #: 674902551

Weld County, CO

NESW Section 22 T3N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /3N65W22
Location ID: 318026



Photo 1. Photo taken from the access road looking into the location, facing North. Appears Operator has not performed final reclamation activities with equipment still on location.



Photo 2. Photo taken from the location, facing West. See comments from Photo 1.