

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401924669

Date Received:

02/12/2019

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

461961

SPILL/RELEASE REPORT (INITIAL /w SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPOperator No: 47120Address: P O BOX 173779City: DENVERState: COZip: 80217-3779Contact Person: Gregory Hamilton

Phone Numbers

Phone: (970) 336-3500Mobile: (970) 515-1698Email: Gregory.Hamilton@ana-darko.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401924669Initial Report Date: 01/31/2019Date of Discovery: 03/03/2014Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWNE SEC 23 TWP 3N RNG 66W MERIDIAN 6Latitude: 40.212433 Longitude: -104.736178Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: TANK BATTERY☐ Facility/Location ID No _____

Spill/Release Point Name: _____

☒ No Existing Facility or Location ID No.

Number: _____

☐ Well API No. (Only if the reference facility is well) 05- _____

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0Estimated Condensate Spill Volume(bbl): >=5 and <100Estimated Flow Back Fluid Spill Volume(bbl): 0Estimated Produced Water Spill Volume(bbl): 0Estimated Other E&P Waste Spill Volume(bbl): 0Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: _____

Land Use:

Current Land Use: NON-CROP LAND

Other(Specify): _____

Weather Condition: 40 degrees F.Surface Owner: FEE

Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On March 9, 2014, approximately 30 barrels of condensate were released inside secondary containment at the Sarchet 41-23, Sarchet UPRR 42-23 3X production facility when a motor valve seat and trim failed at the wellhead. Approximately 25 barrels of condensate were recovered via vacuum truck and transferred to a licensed injection facility for disposal. Excavation activities were guided in the field by screening soil for volatile organic compound (VOC) concentrations using a photoionization detector (PID). A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
3/9/2014	County	Roy Rudisill	-email	
3/9/2014	County	David Bauer	-email	

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/31/2019		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	30	25	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>

specify: _____

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) ☒ Soil ☐ Groundwater ☐ Surface Water ☐ Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 41 Width of Impact (feet): 36

Depth of Impact (feet BGS): 6 Depth of Impact (inches BGS): _____

How was extent determined?

On March 9, 2014, approximately 30 barrels of condensate were released inside secondary containment at the Sarchet 41-23, Sarchet UPRR 42-23 3X production facility. Approximately 160 cubic yards of impacted material were removed and transported to the Buffalo Ridge Landfill in Keenesburg, Colorado for disposal. Eight (8) confirmation soil samples were collected from the sidewalls and base of the final extent of the excavation area at depths ranging from approximately 4 feet to 6 feet below ground surface (bgs). The soil samples were submitted to eAnalytics Laboratory for analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), total petroleum hydrocarbons (TPH) - gasoline range organics (GRO) by USEPA Method 8260C, TPH - diesel and oil range organics (DRO and ORO) by USEPA Method 8015. Laboratory analytical results indicated that constituent concentrations in the soil samples collected from the final extent of the excavation area were in full compliance with COGCC standards. A topographic Site Location Map showing the geographic setting of the release is provided as Figure 1. Soil sample locations are illustrated on Figure 2. Soil analytical results are summarized in Table 1 and the laboratory analytical reports are provided as Attachment A. A Form 27 Site Investigation and Remediation Workplan - Produced Water Vessel Closure Report will be prepared for this release.

Soil/Geology Description:

Title: Senior Staff Env Rep Date: 02/12/2019 Email: Gregory.Hamilton@anadarko.com

<u>COA Type</u>	<u>Description</u>

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
401924669	SPILL/RELEASE REPORT(I/S)
401925086	TOPOGRAPHIC MAP
401925096	ANALYTICAL RESULTS
401925098	ANALYTICAL RESULTS
401926347	SITE MAP
401937760	FORM 19 SUBMITTED

Total Attach: 6 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)