

Final Reclamation and Stormwater Inspection

February 8, 2019

Operator: NOBLE ENERGY INC – 100322

Location ID: 405904

Inspection Document #: 674902555

Weld County, CO

SWSW Section 27 T3N R65W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /3N65W27
Location ID: 405904



Photo 1. Photo taken from the location, facing Northwest. Appears Operator is in the process of removing the riser at east end of battery location but is still on location.



Photo 2. Photo taken from the location. See comments from Photo 1.