

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/12/2019

Submitted Date:

02/12/2019

Document Number:

692601359

**FIELD INSPECTION FORM**

Loc ID 303310 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69760  
Name of Operator: PETRON DEVELOPMENT COMPANY  
Address: 1899 W LITTLETON BLVD  
City: LITTLETON State: CO Zip: 80120

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Walker, Jimmy	(303) 794-5300	jim@petron.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252880	WELL	PR	05/14/1990	GW	125-06756	F. QUICK-PETERS 23-1	PR

**General Comment:**

[Routine Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign mounted to meter shed		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign mounted to wellhead		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:			
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Separator	# 1		
Comment:	HGS on north side of meter shed		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator 50% buried on north side of meter shed		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Meter shed is 865' west of wellhead		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 252880 Type: WELL API Number: 125-06756 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Meter run is 865' west of wellhead](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat: 39.949840      Long: -102.392310

Reference Point: SE      Other: \_\_\_\_\_      Length: 20      Width: 10

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action       Date: \_\_\_\_\_

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action       Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action       Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: \_\_\_\_\_      2+ feet Freeboard: \_\_\_\_\_

Comment:

Corrective Action       Date: \_\_\_\_\_