

Inspection Photos

Location Name: MOORE 3-11 MH

Location ID: 05-103-09032

Inspection: 679702977



Photo 1. Location looking west.



Photo 2. Pressure gauge leaking gas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: MOORE 3-11 MH

Location ID: 05-103-09032

Inspection: 679702977



Photo 3. NFPA label not legible.



Photo 4. Contents not legible & no secondary containment for barrel.