

Inspection Photos

Location Name: BUNN I-66N66W /35SESW

Location #: 305635



Photo #1

Bunn I 35-14 (05-123-23285) Wellsite

Plugged & Abandoned | PA

Unused Riser



Photo #2

Bunn I 35-14 Wellsite

Unused Equipment



Inspection Photos

Location Name: BUNN I-66N66W /35SESW

Location #: 305635



Colorado Oil & Gas Conservation Commission
40.43874, -104.7464, 1414.0m, 135°
2019/02/12 03:49:14 PM

Photo #3
Bunn I 35-14 Wellsite
Unused Equipment



Colorado Oil & Gas Conservation Commission
40.43874, -104.7464, 1414.0m, 276°
2019/02/12 03:49:25 PM

Photo #4
Bunn I 35-14 Wellsite
Unused Equipment

