

Final Reclamation Inspection

February 11, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 335664

Inspection Document #: 682404509

Weld County, CO

NWSW Section 19 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VESSELS #23-19
Location ID: 335664



Photo 1. Photo taken from the PA well location, facing West. No visual evidence of oil and gas equipment on location. Vegetative assessment could not be performed because of snow cover.

Inspection Photos
Location Name: VESSELS #23-19
Location ID: 335664



Photo 2. Photo taken from the PA well location, facing South. See comments under Photo 1.