

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Ester #1 location photo.



Pit ID #119826

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Ester #1 well head.

Power supply panel and debris near well head.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Gas supply line coming off of well head.



Stained soil scooped up from western edge of pit.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



2" stand pipe adjacent to pit area.



Discolored mound along southern edge of location.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Drop out tank and other debris near well head.



Power line road at western edge of location.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Undisturbed area to the west of Ester #1 location.



Electrical panel on location.

Inspection Photos
Location Name: Ester #1
API: 05-067-06232



Rig anchor observed in NE corner of location.



Remnants of access road in NE corner.