

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/14/2019

Submitted Date:

02/14/2019

Document Number:

692601384

FIELD INSPECTION FORM

Loc ID 337556 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286797	WELL	PR	02/29/2008	GW	125-10339	WESTERBERG 31-7	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:			Date:
Type	OTHER		
Comment:	Lease sign by water tank		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input style="width: 500px; height: 20px;" type="text"/>	
Corrective Action:	<input style="width: 500px; height: 20px;" type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Metal panels around meter shed and VGS		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:			Date:

Equipment:				corrective date
Type: Gas Meter Run	# 5			
Comment:	Shared meter run for Westerberg 31-7, 32-7, 41-7, 42-7 and Cantrell 6-16 730' northeast of wellhead			
Corrective Action:				Date:
Type: Vertical Separator	# 5			
Comment:	5-Vertical gas separators 50% buried by meter shed			
Corrective Action:				Date:

Type: Ancillary equipment	# 2	
Comment:	Gas scrubber and telemetry equipment at meter shed	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	Churchill unit	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Arrow gas engine	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		39.991420,-102.340500
Comment:	Fiberglass water tank 50% buried on east side of meter shed				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbbs
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 286797 Type: WELL API Number: 125-10339 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Westerberg 31-7, 32-7, 41-7, 42-7 and Cantrell 6-16\) 730' NE of wellhead on S side of CR 29](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT