

Maralex Resources Inc.

Api # 05-077-08493

Inspection # 675001940



Location Photo

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675001940



Tank Photo . (labels warn faded, Rubbish inside of berm.)



Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675001940



Rubbish inside of berm. Berm walls are washing away.

Maralex Resources Inc.

Api # 05-077-08493

Inspection # 675001940



Well Head Photo (No wellhead sign)



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675001940



Empty fenced pit



Empty fenced Pit

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675001940



Separator

Maralex Resources Inc.
Api # 05-077-08493
Inspection # 675001940



Unused, unmarked, locked out tagged out riser

