

# Stormwater Inspection

February 15, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP- #47120

Location ID: 321432

Inspection Document #: 682404525

Boulder County, CO

NENW Section 34 T2N R69W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MCCARTY #MB 34-3  
Location ID: 321432



**Photo 1.** Photo taken from the entrance of the location off Niwot Rd. on 2/13/19, facing East. No tracking device BMP's installed or not adequately maintained to prevent track of material offsite.

Inspection Photos  
Location Name: MCCARTY #MB 34-3  
Location ID: 321432



**Photo 2.** Photo taken from the entrance of the location off Niwot Rd. on 2/15/19, facing West. Photo illustrates no track out was observed at the time of this inspection. Operator dispatched a street sweeper to clean track out on 2/13.



**Photo 3.** Photo taken from the entrance of the location off Niwot Rd. on 2/15/19, facing East. See comments under Photo 2.