

Caerus Piceance LLC  
Api # 05-077-10072  
Inspection # 675001960



Location Photo

Caerus Piceance LLC  
Api # 05-077-10072  
Inspection # 675001960



**Wellhead Photo**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Piceance LLC  
Api # 05-077-10072  
Inspection # 675001960



**Tank Battery photo**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
Api # 05-077-10072  
Inspection # 675001960



Unused equipment or trash stored on location