

Inspection Photos

Location Name: M.V. SMITH 31-9

Location ID: 05-103-05344

Inspection: 679703017



Photo 1. Location looking north.



Photo 2. Location looking north.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: M.V. SMITH 31-9
Location ID: 05-103-05344
Inspection: 679703017



Photo 3. Tank label incomplete.



Photo 4. Tank label incomplete.

Inspection Photos

Location Name: M.V. SMITH 31-9

Location ID: 05-103-05344

Inspection: 679703017




Photo 5. Tank label incomplete.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources