

**Inspection Photos**  
**Location Name: F.V. LARSON B 19X**  
**Location ID: 05-103-07106**  
**Inspection: 679703021**



**Photo 1. Location looking northwest.**



**Photo 2. Deadman marker lying down.**