

Inspection Photos

Location Name: HARRINGTON-66N66W /30SEnw

Location #: 319016



Colorado Oil & Gas Conservation Commission
40.4593, -104.82242, 1432.0m, 260°
2019/02/13 03:51:33 PM

Photo #1

Harrington 1-30 (05-123-10495) Wellsite

Shut-In | SI

No sign with contact or emergency number posted



Colorado Oil & Gas Conservation Commission
40.45857, -104.82307, 1438.0m, 278°
2019/02/13 04:12:52 PM

Photo #2

Harrington 1-30 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HARRINGTON-66N66W /30SEnw

Location #: 319016



Colorado Oil & Gas Conservation Commission
40.4593, -104.82242, 1432.0m, 260°
2019/02/13 03:51:33 PM

Photo #3

Harrington 1-30 Wellsite

Unused full drum – contents unknown

Unused Equipment: Bridle, sucker rod



Colorado Oil & Gas Conservation Commission
40.45857, -104.82307, 1438.0m, 278°
2019/02/13 04:12:52 PM

Photo #4

Harrington 1-30 Battery

No berm around 210 Bbls. crude oil tank



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HARRINGTON-66N66W /30SENW

Location #: 319016



Photo #5

Harrington 1-30 Wellsite

Stained soil beneath pump jack gearbox

Stained soil near engine house



Photo #6

Harrington 1-30 Battery

Stained soil near crude oil tank load-out

Inspection Photos

Location Name: HARRINGTON-66N66W /30SENW

Location #: 319016



Photo #7

Harrington 1-30 Battery

No contact or emergency number posted



Photo #8

Harrington 1-30 Battery

***Unused Equipment | Junk / Trash
Tanks, separator, pipes, hoses, stairway***



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HARRINGTON-66N66W /30SENW

Location #: 319016



Photo #9
Harrington 1-30 Battery
Storage trailer



Photo #10
Harrington 1-30 Battery
Aggregate

