

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401942641

Date Received:

02/16/2019

Spill report taken by:

Graber, Candice
(Nikki)

Spill/Release Point ID:

461898

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: <u>BONANZA CREEK ENERGY OPERATING COMPANY LLC</u>	Operator No: <u>8960</u>	Phone Numbers
Address: <u>410 17TH STREET SUITE #1400</u>		Phone: <u>(720) 4406100</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Brian Dodek</u>		Mobile: <u>()</u>
		Email: <u>BDodek@Bonanzacrk.com</u>

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 401931277

Initial Report Date: 02/06/2019 Date of Discovery: 01/25/2019 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR NWSW SEC 17 TWP 5N RNG 62W MERIDIAN 6

Latitude: 40.397803 Longitude: -104.353357

Municipality (if within municipal boundaries): _____ County: WELD

Reference Location:

Facility Type: WELL PAD ☒ Facility/Location ID No 420920
 Spill/Release Point Name: ANT 13-17 Offpad Discharge ☐ No Existing Facility or Location ID No.
 Number: _____ ☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes
*Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.*

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): >=5 and <100 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Unknown illegal discharge (Non-Bonanza) of fluid

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): _____

Weather Condition: 22 degrees, clear

Surface Owner: FEE Other(Specify): _____

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

Bonanza creek personnel reported a suspicious looking fluid transport truck parked on a remote location. Later in the day personnel stopped at the location to investigate. Bonanza personnel observed tire tracks backed to the edge of the location and evidence of a fluid discharge off location into the adjacent grassland. Bonanza contacted the COGCC to verbally report the release. The Form 19 was not submitted immediately as Bonanza set up surveillance equipment to attempt to catch a subsequent event in progress. If caught, Bonanza would have asked the guilty party to report the release. Bonanza did not observe any additional discharge events and we are submitting a Form 19 to report the illegal discharge and begin cleanup of the release.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
2/6/2019	Landowner	70 Ranch	-on file	Notified of release

Was there a Grade 1 Gas Leak associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Grade 1 Gas Leak Report Form 44: _____

Was there a reportable accident associated with this E & P waste spill or release? Yes ☐ No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: _____

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 02/16/2019		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE			<input checked="" type="checkbox"/>
specify: Unknown illegal discharge (Non-Bonanza) of fluid			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, including walls & floor regardless of construction material , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): 120		Width of Impact (feet): 15	
Depth of Impact (feet BGS):		Depth of Impact (inches BGS):	
How was extent determined?			
The extent of the release was determined through visual delineation.			
Soil/Geology Description:			
Valent sand, 3-9% slopes			
Depth to Groundwater (feet BGS) 25		Number Water Wells within 1/2 mile radius: 1	
If less than 1 mile, distance in feet to nearest		Water Well 1921	None <input type="checkbox"/> Surface Water None <input checked="" type="checkbox"/>
		Wetlands	None <input checked="" type="checkbox"/> Springs None <input checked="" type="checkbox"/>
		Livestock	None <input checked="" type="checkbox"/> Occupied Building None <input checked="" type="checkbox"/>

Additional Spill Details Not Provided Above:

Due to an internal investigation aimed at catching the responsible party for the illegal dumping, spill clean up was delayed. Remediation is currently underway. Confirmation soil samples will be collected and submitted for laboratory analysis. Analytical results will be included in a subsequent F19.

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

The depth to water is estimated due to a lack of static water levels surrounding the release points on COGIS.

The release dimensions provided are estimated to match the largest of the release footprints.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Brian Dodek

Title: Env. Manager Date: 02/16/2019 Email: BDodek@Bonanzacrk.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

401942642	SITE MAP
-----------	----------

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)