

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



Feb 13, 2019 10:28:24
38.81318N 102.06880W

Stained soil inside containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



Rabbit burrow in tank battery containment wall.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



Rabbit burrow in tank battery containment wall.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



Gas observed to be venting from open pipe.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: White AG Tank Battery Facility #462031 Inspection Date: 2/13/2019



Feb 13, 2019 10:29:54
38.81313N 102.06879W

Gas observed to be venting from open pipe.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources