

Final Reclamation and Stormwater Inspection

February 13, 2019

Operator: NOBLE ENERGY INC # 100322

Location ID: 318994

Inspection Document #: 674902580

Weld County, CO

NWNW Section 9 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NOBLE ENERGY INC /2N68W9
Location ID: 318994



Photo 1. Photo taken from CR 7 looking into the access road, facing West. Appears the access road has not been reclaimed.



Photo 2. Photo taken from the access road, facing East. See comments from Photo 1.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N68W9
Location ID: 318994



Photo 3. Photo taken from the location, facing South. See comments from Photo 1. Appears the Operator has performed final reclamation activities with the evidence of some vegetation growth and straw waddle BMPs that remain on site.



Photo 4. Photo taken from the well location. Photo depicts areas of gravel left on site.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N68W9
Location ID: 318994



Photo 5. Photo taken from the location, facing South. Erosion control waddles left on site are deteriorating.



Photo 6. Photo taken from the location, facing South. Appears guy wire anchor and gravel is left on location.

Inspection Photos
Location Name: NOBLE ENERGY INC /2N68W9
Location ID: 318994



Photo 7. Photo taken from the location, facing Northeast. Appears the location has undesirable species and the reclamation is not at percent cover and has non-uniform establishment of perennial cover.



Photo 8. Photo taken from the location, facing West. Appears a gas gathering riser remains on location.