

Final Reclamation and Stormwater Inspection

February 13, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 323697

Inspection Document #: 674902581

Weld County, CO

SENE Section 15 T2N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /1N65W15

Location ID: 323697



Photo 1. Photo taken from the location, facing East. Appears the Operator has performed final reclamation activities. However, several locations throughout the site lack uniform perennial vegetation and are covered in weedy, annual vegetation which includes but not limited to kochia.



Photo 2. Photo taken from the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: CRESTONE PEAK RESOURCES /1N65W15

Location ID: 323697



Photo 1. Photo taken from the location, facing Southeast. See comments from Photo 1.



Photo 2. Photo taken from the location, facing Southeast. See comments from Photo 1.