

Valkyrie Resources LLC, Jones-Dupree 1
121-05415

Inspection #688303797

2/13/2019

Routine Inspection



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources



JONES-DUPREE 1

API# 05-121-05415

SWNE Sec 26 T3S R51W

IN CASE OF EMRGENCY CALL:

IN

1-303-996-7766

OR AFTER HOURS:

1-307-388-2290 OR 911

LL:

02.13.2019



02.13.2019



SAGA PETROLEUM

For Emergency Call: (303)996-7766 or 911

Leases: Jones, Jones JW, Jones Dupree

HWY 63 & HWY 36, E 2 TO RD 12,

E @ Y, 7 M TO RD MM, N 1.7 & W INTO

SENW Sec 26 T3S R51W

02.13.2019



02.13.2019



02.13.2019


SAGA *PETROLEUM*

In Case of Emergency Call:
(303)996-7766



Capacity: 400 BBL
Contents: Crude Oil

02.13.2019



SAGA PETROLEUM

In Case of Emergency Call:
(303)996-7766



Capacity: 400 BBL
Contents: Crude Oil

02.13.2019


SAGA PETROLEUM

In Case of Emergency Call:
(303)996-7766



Capacity: 400 BBL
Contents: Crude Oil

02.13.2019



SAGA PETROLEUM

In Case of Emergency Call:
(303)996-7766



Capacity: 400 BBL
Contents: Crude Oil

02.13.2019



02.13.2019



Truck loadout
requires bird
cover.

02.13.2019



02.13.2019



02.13.2019



400 BBL
WATER
1

02.13.2019

400 BBL
WATER
Z



SAGA PETROLZUM
IN CASE OF EMERGENCY
CALL 1-303-986-7766

02.13.2019



400 BBL
WATER

3

02.13.2019

10 BBL
WATER

4




02.13.2019



02.13.2019



02.13.2019

A photograph of an industrial site. In the foreground, there is a large pile of brown, stained soil. To the left, a large, vertical, cylindrical tank is heavily rusted and has a green base. A green building with a single window and a door is attached to the side of the tank. A grey electrical control box is mounted on the green building's wall. In the background, there is a flat, open landscape under a cloudy sky. A small green structure and a blue container are visible to the right of the main building.

Stained soil.

02.13.2019



Leaking valves
in east treater
shed and full
buckets of oil.

02.13.2019



02.13.2019



02.13.2019

A photograph showing the exterior corner of a shed. The shed's walls are made of green corrugated metal. The ground is a mix of light brown dirt and gravel. A dark, irregular stain is visible on the gravel in the foreground, near the corner of the shed. A white pipe or vent protrudes from the ground near the shed's base. In the background, a grey corrugated metal base or foundation runs along the perimeter. A white electrical box is mounted on a post in the upper right corner. The text "Stained soil at FWKO shed." is overlaid in the center of the image.

Stained soil at FWKO shed.

02.13.2019

Oil on 1500 bbl tank.

02.13.2019

1500

02.13.2019

1500


BBL

02.13.2019

1500

BBL

02.13.2019



Emergency pit.

02.13.2019