

Inspection Photo (s)
North Bank C-7
API # 05-045-13618
Inspection # 689303263



Location Photo #1



Location Photo #2

Inspection Photo (s)
North Bank C-7
API # 05-045-13618
Inspection # 689303263



Location Photo #3



Location Photo #4, Stained ground at blow down at separator.

Inspection Photo (s)
North Bank C-7
API # 05-045-13618
Inspection # 689303263



Location Photo #5, Condensate in drip pan.



Location Photo #6, free floating condensate in battery containment.

Inspection Photo (s)
North Bank C-7
API # 05-045-13618
Inspection # 689303263



**Location Photo #7, free floating condensate
in battery containment.**