

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2019

Submitted Date:

02/15/2019

Document Number:

689303253**FIELD INSPECTION FORM**

|  |                                 |   |                   |   |
|--|---------------------------------|---|-------------------|---|
| Loc ID<br>334649   | Inspector Name:<br>Holtz, Darin | On-Site Inspection <input type="checkbox"/> | 2A Doc Num: _____ | <b>Status Summary:</b><br><input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION<br><input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED<br><input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED<br><br><b>Findings:</b><br>17 Number of Comments<br>0 Number of Corrective Actions<br><input type="checkbox"/> Corrective Action Response Requested |
| <b>Operator Information:</b><br>OGCC Operator Number: <u>10456</u><br>Name of Operator: <u>CAERUS PICEANCE LLC</u><br>Address: <u>1001 17TH STREET #1600</u><br>City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u> |                                 |   |                   | <b>ANY CORRECTIVE ACTION(S) FROM<br/>PREVIOUS INSPECTIONS THAT HAVE NOT<br/>BEEN ADDRESSED ARE STILL APPLICABLE</b>   |

| <b>Contact Information:</b> |              |   |                                 |
|-----------------------------|--------------|---|---------------------------------|
| Contact Name                | Phone        | Email                                     | Comment                         |
| Rider, Lindsay              | 970-285-2711 | cogcc.inspections@caerusoila<br>ndgas.com | <a href="#">All Inspections</a> |

| <b>Inspected Facilities:</b> |      |        |             |            |           |                 |             |
|------------------------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| Facility ID                  | Type | Status | Status Date | Well Class | API Num   | Facility Name   | Insp Status |
| 265640                       | WELL | PR     | 10/19/2003  | GW         | 045-09042 | GMR 4-16D (M3A) | PR          |
| 265641                       | WELL | PR     | 10/17/2003  | GW         | 045-09043 | GMR 3-11B (M3A) | PR          |
| 265642                       | WELL | PR     | 08/29/2003  | GW         | 045-09044 | GMR 9-1D (M3A)  | PR          |
| 265643                       | WELL | PR     | 10/15/2003  | GW         | 045-09045 | GMR 4-9D (M3A)  | PR          |
| 265645                       | WELL | PR     | 09/08/2003  | GW         | 045-09046 | GMR 3-13D (M3A) | PR          |
| 265646                       | WELL | PR     | 10/10/2003  | GW         | 045-09047 | GMR 3-13A (M3A) | PR          |
| 265647                       | WELL | PR     | 08/28/2003  | GW         | 045-09048 | GMR 3-13B (M3A) | PR          |
| 266010                       | WELL | PR     | 09/10/2003  | GW         | 045-09051 | HMU 3-14D (M3A) | PR          |
| 266011                       | WELL | PR     | 09/05/2003  | GW         | 045-09049 | HMU 10-3B (M3A) | PR          |
| 266012                       | WELL | PR     | 10/13/2003  | GW         | 045-09050 | HMU 3-14B (M3A) | PR          |
| 273556                       | WELL | PR     | 11/26/2005  | GW         | 045-10260 | GMR 3-12D (M3A) | PR          |
| 273557                       | WELL | PR     | 12/01/2005  | GW         | 045-10261 | GMR 3-13C (M3A) | PR          |

|  |
|--|
| <b>General Comment:</b><br><a href="#">Routine Field Inspection.</a> |
|--|

**Location**

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Lease Road:</b> |              |       |  |
| Type               | Access       |       |  |
| comment:           | Snow packed. |       |  |
| Corrective Action  | L            | Date: |  |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |        |       |  |
|--------------------|--------|-------|--|
| Type               | DEBRIS |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |
| Type               | TRASH  |       |  |
| Comment:           |        |       |  |
| Corrective Action: |        | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

|                                 |      |       |                 |
|---------------------------------|------|-------|-----------------|
|                                 |      |       | corrective date |
| Type: Gas Meter Run             | # 1  |       |                 |
| Comment:                        |      |       |                 |
| Corrective Action:              |      | Date: |                 |
| Type: Vertical Heated Separator | # 12 |       |                 |
| Comment:                        |      |       |                 |
| Corrective Action:              |      | Date: |                 |
| Type: Plunger Lift              | # 12 |       |                 |
| Comment:                        |      |       |                 |
| Corrective Action:              |      | Date: |                 |
| Type: Bird Protectors           | # 3  |       |                 |
| Comment:                        |      |       |                 |
| Corrective Action:              |      | Date: |                 |
| Type: Deadman # & Marked        | # 12 |       |                 |
| Comment:                        |      |       |                 |
| Corrective Action:              |      | Date: |                 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |  |
|--------------------|---|----------|-----------|---------|--------|--|
| CONDENSATE         | 3 | 300 BBLs | STEEL AST |         | ,      |  |
| Comment:           |   |          |           |         |        |  |
| Corrective Action: |   |          |           |         | Date:  |  |

**Paint**

|                  |               |  |
|------------------|---------------|--|
| Condition        | Adequate      |  |
| Other (Content)  | Methanol tank |  |
| Other (Capacity) | 1000 gallon.  |  |
| Other (Type)     |               |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities  |                                 |       |      |             |           |         |    |               |    |
|-----------------------|---------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 265640                          | Type: | WELL | API Number: | 045-09042 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265641                          | Type: | WELL | API Number: | 045-09043 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265642                          | Type: | WELL | API Number: | 045-09044 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265643                          | Type: | WELL | API Number: | 045-09045 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265645                          | Type: | WELL | API Number: | 045-09046 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265646                          | Type: | WELL | API Number: | 045-09047 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 265647                          | Type: | WELL | API Number: | 045-09048 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |                                 |       |      |             |           |         |    |               |    |
| Comment:              | Well Producing on plunger lift. |       |      |             |           |         |    |               |    |
| Corrective Action:    |                                 |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 266010                          | Type: | WELL | API Number: | 045-09051 | Status: | PR | Insp. Status: | PR |

| <b><u>Producing Well</u></b>   |                                 |       |  |
|--|---------------------------------|-------|--|
| Comment:   | Well Producing on plunger lift. |       |  |
| Corrective Action:   |                                 | Date: |  |
| Facility ID: 266011    Type: WELL    API Number: 045-09049    Status: PR    Insp. Status: PR |                                 |       |  |
| <b><u>Producing Well</u></b>   |                                 |       |  |
| Comment:   | Well Producing on plunger lift. |       |  |
| Corrective Action:   |                                 | Date: |  |
| Facility ID: 266012    Type: WELL    API Number: 045-09050    Status: PR    Insp. Status: PR |                                 |       |  |
| <b><u>Producing Well</u></b>   |                                 |       |  |
| Comment:   | Well Producing on plunger lift. |       |  |
| Corrective Action:   |                                 | Date: |  |
| Facility ID: 273556    Type: WELL    API Number: 045-10260    Status: PR    Insp. Status: PR |                                 |       |  |
| <b><u>Producing Well</u></b>   |                                 |       |  |
| Comment:   | Well Producing on plunger lift. |       |  |
| Corrective Action:   |                                 | Date: |  |
| Facility ID: 273557    Type: WELL    API Number: 045-10261    Status: PR    Insp. Status: PR |                                 |       |  |
| <b><u>Producing Well</u></b>   |                                 |       |  |
| Comment:   | Well Producing on plunger lift. |       |  |
| Corrective Action:   |                                 | Date: |  |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: [Location is snow covered.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                | URL   |
|--------------|----------------------------|---|
| 689303260    | Inspection photo 689303260 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737946">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4737946</a> |