

Final Reclamation Inspection

February 13, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 321300

Inspection Document #: 682404533

Boulder County, CO

SESE Section 26 T2N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CALDWELL K UNIT 62N69W / /26
SESE
Location ID: 321300



Photo 1. Photo taken from the production/well location, facing South. This production facility serves two wells.

Inspection Photos
Location Name: CALDWELL K UNIT 62N69W / /26
SESE
Location ID: 321300



Photo 2. Photo taken from the production/well location, facing West. Photo illustrates only one well was drilled at the location- CALDWELL K UNIT # 1.