

Interim Reclamation and Stormwater Inspection

February 13, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 321300

Inspection Document #: 682404535

Boulder County, CO

SESE Section 26 T2N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CALDWELL K UNIT 62N69W / /26
SESE
Location ID: 321300



Photo 1. Photo taken from the production/well location, facing Southwest. Operator has failed to stabilize production areas per Rule 1003.b. Photo illustrates erosion along the perimeter of the production area.

Inspection Photos
Location Name: CALDWELL K UNIT 62N69W / /26
SESE
Location ID: 321300



Photo 2. Photo taken from the production/well location, facing South. See comments under Photo 1.