

Inspection Photos

Operator: Kinder Morgan
Location/API #: 083-06649
Date: 2/13/2019



Photo 1. View of the southern project area from the southwestern corner facing eastward.



Photo 2. View of musk thistle debris within the southern interim reclamation area.