

# Inspection Photos

Operator: Kinder Morgan  
Location/API #: 083-06438  
Date: 2/13/2019



Photo 1. View of the northern project area from the northwestern corner facing eastward. Berm appears to be functioning.



Photo 2. View of revegetation area recently seeded adjacent to the southern project area, from the southwestern corner facing eastward. Revegetation appears to be progressing.