

Final Reclamation Inspection

February 15, 2019

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 321434

Inspection Document #: 682404541

Boulder County, CO

SENE Section 34 T2N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: VANTHUYNE #42-34
Location ID: 321434



Photo 1. Photo taken from the PA well location, facing East. No equipment was observed at the location. A vegetative assessment was not performed because crop field is currently fallow.

Inspection Photos
Location Name: VANTHUYNE #42-34
Location ID: 321434



Photo 2. Photo taken from the PA well location, facing West. See comments under Photo 1.