

Final Reclamation Inspection

February 15, 2019

Operator: EXTRACTION OIL & GAS INC - #10459

Location ID: 328007

Inspection Document #: 682404547

Weld County, CO

SWSE Section 31 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: CINQUE-62N68W 31SWSE
Location ID: 328007



Photo 1. Photo taken from the PA well location, facing East. Final land use change to gravel mine.



Photo 2. Photo taken from the production facility, facing East. Active meter shed is still present. A Final Reclamation inspection will not be passed until all equipment is removed.

