

Inspection Photos

Location Name: NORTH DOUGLAS CREEK 13-33-1-1

Location ID: 05-103-08435

Inspection: 679703029



Photo 1. Location looking northeast.



Photo 2. Uncapped riser.



Inspection Photos

Location Name: NORTH DOUGLAS CREEK 13-33-1-1

Location ID: 05-103-08435

Inspection: 679703029



Photo 3. Smell of gas at well head.

