

Construction and Storm Water Inspection

February 15, 2019

Operator: BURLINGTON RESOURCES OIL & GAS LP – 26580

Location ID: 455758

Inspection Document #: 674902572

Arapahoe County, CO

SWNE Section 8 T4S R64W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 1. Photo taken from the entrance of the location, facing Northwest. Operator has begun construction on the location and access road.



Photo 2. Photo taken from the location, facing West. Photo illustrates the topsoil stockpile being stored along the eastern area and has been temporarily stabilized with equipment tracking.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 3. Photo taken from the southeastern perimeter of the location, facing North. Photo illustrates a filtrex BMP that has been installed around the entire perimeter of the location in conjunction with other BMPs.



Photo 4. Photo taken from the southeastern perimeter of the location, facing West. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 5. Photo taken from the northeastern perimeter of the location, facing West. See comments from Photo 1.



Photo 6. Photo taken from the northeastern perimeter of the location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 7. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1.



Photo 8. Photo taken from the northwestern perimeter of the location, facing South. See comments from Photo 1

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 9. Photo taken from the northwestern perimeter of the location, facing South. See comments from Photo 1



Photo 10. Photo taken from the northwestern perimeter of the location, facing East. See comments from Photo 1

Inspection Photos

Location Name: BURLINGTON RESOURCES OIL & GAS LP /4S64W8

Location ID: 455758



Photo 11. Photo taken from the southwestern perimeter of the location, facing North. See comments from Photo 1



Photo 12. Photo taken from the southern perimeter of the location, facing West. See comments from Photo 1