

Inspection Photos
Location Name: Log Cabin 1
Location ID: 332855




Photo 1: Wellhead with excessive amount of weed growth.



Photo 2: Leaking polish rod from conventional pumping unit

Inspection Photos
Location Name: Log Cabin 1
Location ID: 332855



Photo 3: Unused equipment.