

Inspection Photos

Location Name: FEDERAL RGU 31-30-198

Location ID: 05-103-10633

Inspection: 679703042



Photo 1. Location looking east.



Photo 2. Casing valve leaking gas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources